

Contents:

- [How to check software version](#) (if applicable)
- [How to update software](#) (if applicable)
- [How to do a WiFi Map Update](#)


ELIGIBLE MODELS

Vehicle Model	Vehicle Model Year	Wi-Fi Map Update Capability Available?
RDX	2019-2021	NO
	2022-2023	*YES once software is updated
	2024-2026	YES
MDX	2022-2023	*YES once software is updated
	2024	YES
TLX	2021-2023	NO
	2024-2025	YES

*For these models, Acura pushed out the Wi-Fi map update feature via an Over the Air Software update to vehicles. Owners would have to install this update and have software version: F.1.3.3 or F.1.4.1

*HOW TO CHECK SOFTWARE VERSION

- 1) In your navigation system -press the Home Button 
- 2) Go to **'Settings'** then **'System'** then **'About'**
- 3) Scroll down and the 'version' should be shown on the bottom of the menu. 'Acura Software Version' starts with "D" or "F"
- 4) If version is F.1.3.3 or F.1.4.1 – then WiFi map update capability should be available





*HOW TO UPDATE SOFTWARE VERSION

Please note: HERE Technologies does not support software update questions. If you require additional support with Acura Software - please contact Acura Client Services or go to <https://mygarage.honda.com/s/find-acura>

WiFi connection is required for this process:

- 1) Press Home button 
- 2) Select '**System Updates**' (you will see a '!' on the System Updates icon if there are updates)
- 3) Select '**Via Wireless Connection.**' When the download is complete, the screen for step #4 will be displayed
- 4) Select '**Download Now.**' A notification will appear on the screen



Important: Anytime your engine is running – please ensure the vehicle is in a well-ventilated area to avoid carbon monoxide poisoning

If applicable – there are two convenient map update options included with your active subscription:

- 1) **USB Download: Full Map Update.** (Install guide is available on the webstore)
Includes entire region (North America for example) - downloaded to a USB flash drive. Map is downloaded via the webstore
- 2) **Wi-Fi Update: Regional Update – see instructions below:** Includes a smaller coverage area that can be updated through a Wi-Fi connection — no USB required.

To get started on a Wi-Fi update:

a) WiFi and 'Connected Features' must be enabled

1. Connect your vehicle's navigation system to **Wi-Fi**
 - a) Press the **Home** button
 - b) Select **Settings** → **Connections** → **Wi-Fi** → **Change Mode** → **Network**
 - c) Choose a Wi-Fi network and select **Confirm** → **Connect**
 - d) Enter your Wi-Fi password

ENABLE CONNECTED FEATURES

2. Return to **Home** and select **Menu** → **Navigation Menu**
3. Select **Connected Features** to confirm it's enabled
4. Turn off the engine. Your VIN may not be recognized on the webstore until you have waited at least **10–15 minutes** and turned the vehicle back on and off one more time.



- b) Go to '**MENU**', then '**Map Updates**', then '**Automatic Wi-Fi Map Updates**'
- c) Follow the screen prompts. You can check for map updates, or also turn on automatic updates. A Wi-Fi network connection is required for either option

Important: Anytime your engine is running – please ensure the vehicle is in a well-ventilated area to avoid carbon monoxide poisoning

